

# New Holland Sicklebar Mower Specifications

451 456



MODEL	451		456
<b>CUTTERBAR LENGTH</b>	<b>seven-foot</b> 7'3" (2210 mm)	<b>nine-foot</b> 9'3" (2819 mm)	9'3" (2819 mm)
<b>OVERALL LENGTH</b>	3'11" (1188 mm)	3'11" (1188 mm)	7'6" (2286 mm)
<b>OVERALL WIDTH</b>			
operating	12'5" (3785 mm)	14'5" (4395 mm)	15'3" (4648 mm)
transport	6'2" (1870 mm)	7'2" (2175 mm)	7'2" (2175 mm)
<b>HEIGHT</b>			
operating	3'3" (991 mm)	3'3" (991 mm)	3'3" (991 mm)
transport*	5'8" (1715 mm)	6'8" (2032 mm)	6'8" (2032 mm)
<b>WEIGHT, APPROXIMATE</b>	609 lb. (276 kg)	628 lb. (285 kg)	803 lb. (364 kg)
<b>MOWER DRIVE</b>	Heavy-duty V-belt	Heavy-duty V-belt	Heavy-duty V-belt
<b>KNIVES</b>	.....1600 strokes per minute at 540 rpm.....		
speed			
stroke	3.375" (86 mm)	3.375" (86 mm)	3.375" (86 mm)
<b>CUTTERBAR OPERATING RANGE</b>	.....15 degrees below horizontal, 35 degrees above horizontal.....		
<b>TRACTOR REQUIREMENT</b>	.....Fits most CAT I and II 3-point hitch.....		Fits most tractors with standard ASAE drawbar and 540 rpm PTO
	tractors with 540 rpm PTO		

\* plus lift range of tractor

LIFTS: Both lifts operable from the tractor seat. Tractor remote ram required for hydraulic lift on Model 456. Tractor power lift is standard on Model 451.



The mounted 451 has an exclusive telescoping yoke that uses tractor power to lift the mower.



Straight-line motion of the drive head provides fast, smooth cutting combined with less wear on the knife assembly and hold-down clips.

Visit our Web site at [www.newholland.com/na](http://www.newholland.com/na). Or, call toll-free **866-NEW-HLND (866-639-4563)**.

Design, materials and/or specifications are subject to change without notice and without liability therefor. Specifications are applicable to units sold in Canada, the United States, its territories and possessions, and may vary outside these areas.



Safety begins with a thorough understanding of the equipment. Always make sure you and your operators read the Operator's Manual before using the equipment. Pay close attention to all safety and operating decals and never operate machinery without all shields, protective devices and structures in place.